



①




A=6
B=16

②




A=4
B=2

③



B=4

④






LEGEND:

NO	Parts	Fittings	sketch	Qty	Specification
A	Turntable	wood		10*	
B	fitting	wood		18*	
C	Hand	Hand		5*	
D	Full cover	Hand		8*	
B	Screw	Screw		56*	4*16

NO	Parts	Fittings	sketch	Qty	Specification
F	Mail	Mail		30*	
G	Screw	Screw		8*	3*12
H	Aluminum	Aluminum		4*	
J	Screw	Screw		10*	

J=10
K=12

I-1



Product drawing name	Cabinet With 3doors
Install drawing	Install drawing